

## BETHEL PARK – FALL PROJECT LIST ----- October 9 - 12, 2006

### GROUND MAINTENANCE:

Painting: Steel Light Posts (4)  
Electrical: Repair Steel Arch wiring  
Power spray/stain: Flower boxes & benches, River Quiet Bridge Retaining wall  
Trees: Remove – dead trees (12)  
Edge – Evergreens  
Clean out Woods (Condo – Chalet)  
Leaves: Clean out behind Elim Motel  
Nature Walk Way – Complete 2 Mile Trail  
Basketball Backboards: (2) remounted

### HOUSEKEEPING:

Detailed room cleaning: (chalet, elim, condo – etc.)

### DINING ROOM:

Paint touchup – walls  
Paint Entrance doors (int/ext)

### DINING ROOM – MEN’S LAVATORY:

Touch up South Wall

### DINING ROOM STORAGE ROOM:

Install exterior – GFCI + Exit light - rear door  
Install - Emergency Lighting  
Re-stabilize shelving

### KITCHEN - DISHWASHING ROOM:

Complete Tile Baseboard

### KITCHEN – DISH/LAUNDRY ROOM:

Install shelving + finish South wall – hard surface.

### JANITORIAL ROOM:

Complete: Interior/Exterior

### SPRECHER DORM:

Varnish window wells + windows.  
Secure all window crank handles.  
**Clean all AC Filters.**  
**Check - rain gutter + nails.**  
Wall Touch up:  
#3: NWall by Clothes Rack – NW by AC  
WWall by twin bed  
#4: SWall by AC, SWall by Cloths Rack.  
#5. NWall  
#8. NWall, & WWall - **Ceiling Repair.**  
#9. NWall  
#12. NWall - Replace Ceiling Bulb  
Hallway: Replace 60w Globe Bulb  
Linen Room: Repaint Ceiling  
Sky Light Leaks

### CHALET:

Clean A/C filters.  
Mount pictures (4 rooms)  
Remove A/C units in room 2, 3 & 4, (store in Keller #6)  
Install – Screen windows 2, 3 & 4  
Stain exterior  
**Check –rain gutter + nails**  
Room #1 Mount mirrors - Rooms 1,2,3,4  
**Old Bath:** 1<sup>st</sup> Floor: Mount mirror  
**New Bath:** 1<sup>st</sup> Floor: Complete baseboard trim.  
Mount Storage Shelf  
Seal holes in floor: new bathroom + around water heater.

### E.T.MOTEL:

**Check - rain gutter + nails**  
#28. Mount picture  
Redo – vinyl flooring – vanity/bathroom  
#29. Repair baseboard, install door stop.  
#32. Repair baseboard + an extra end table  
#33. Replace Vanity light  
#34. Replace Vanity light, - Threshold rubber seal missing  
#35. Threshold - rubber seal missing

- CONDO:** Clean or replace A/C filters  
**Check - rain gutter + nails**  
 Mount Bathroom wall vents in all 8 units
- LOENSER COTTAGE:** **Check – rain gutter + nails**  
 El. Switch Cover in small bathroom broke (beige)  
 Sewer Clean Out.
- ZELLER COTTAGE:** Dormer – complete siding – cover fascia w/aluminum.  
**Check – rain gutter + nails**
- TABERNACLE:** Repair/repaint Ceiling – NW corner  
**Check – rain gutter + nails**
- POPSTAND:** Close south wall crawl space – cement board  
 Redo/relocate electrical feed to old popstand  
 Install – light switches.  
**Check – rain gutter + nails**  
 Secure windows for winter.
- SHADY NOOK:** Seal water line entrance into lav.  
 Hard surface SW by shower  
 Seal linoleum by shower  
 (3” Frosted Globe bulb, + 25w for table lamp)
- ELIM MOTEL:** #15 – Bunk Bed – replace plywood  
 Remove AC units: # 12, 13, 19, 20, 21  
 Oil Door Locks  
 Repair lower blind bracket (6 doors)  
 Ladies Restroom – window screen missing
- OLD/NEW SHOP:** Repair Metal Roof – Old Shop
- CENTER LAVATORY:** Install Rain Gutter  
 Plumbing Repair

+++++

***As ALWAYS .....Bethel Park..... is the place to be!!***

Your coming would make our day!!! This is a wonderful opportunity  
 to spend time with friends and family!

WELCOME - WILLKOMMEN!!

---