

BETHEL PARK – SPRING WORKWEEK

MAY 8 – 13, 2006 - WORK DETAIL

GROUND MAINTENANCE:

Painting: Popstand - Steel railing

Power spray/stain: Flower boxes & benches
River quiet bridge
Retaining wall

Trees - shrubs: Remove dead pine trees
Remove dead trees – west of office

Electrical: Repair Steel Arch wiring

HOUSEKEEPING:

Detailed room cleaning: (et, chalet, elim, condo)
Wash windows &-shower curtains +wall stains
Clean - furniture & flooring

DINING ROOM:

Paint touchup – walls
Repaint wall – West wall

DINING ROOM STORAGE ROOM

Install In./exterior – El. Receptacles
Install - Emergency Lighting

KITCHEN - DISHWASHING ROOM

Complete ice machine drain plumbing
Extend kitchen sidewalk -- form and pour

SPRECHER DORM:

Varnish window wells + windows.

Secure all window crank handles.

Clean all AC Filters.

Check - rain gutter + nails.

6. Touchup – scuffmarks – south wall

8. **Drywall ceiling repair!**

9. Touchup – scuffmarks – north wall

#10. Touchup – scuffmarks – north and south

SPRECHER DORM: Interior Steps:

Texture and paint walls

Install drop ceiling

CHALET:

Mount Room numbers: 1,2,3, 5

Clean A/C filters.

Install A/C units in room 2, 3 & 4,

Install – Screen windows

Stain & shingle new addition

Paint exterior

Check –rain gutter + nails

#1. Clothes closet – repair drywall & paint.

Mount mirror

#2. Mount mirror

#3. Paint touch up old rack holes

Mount mirror

#4. Paint touch up old rack holes

Mount mirror

#6. Repair Drywall + repaint

Mount mirror

Old Bath: 1st Floor: Mount mirror

New Bath: 1st Floor: Complete baseboard trim.

Mount Storage Shelf

E.T.MOTEL:

Check - rain gutter + nails

#28. Entrance Door – Paint Interior side

#29. Paint - spot/stains: bathroom - north wall

Paint – spots-stain north wall

#31. Paint - South wall –plywood access panel

#33. Paint - bathroom plywood access panel

34. Paint – spots/stains east bathroom wall

#35. Sill - rubber weather stripping missing – door to long??

CONDO:

Paint Exterior doors
Clean or replace A/C filters
Check - rain gutter + nails
#37. Paint - west wall under AC
#39. Door Lock - replace
#40. Paint - scuffmarks behind recliner
Paint scuffmarks - North wall above top bunk
#41. Paint - scuff marks North and west wall
Paint - south wall between bunks
Paint - above of sink & paint – east wall below A/C
#42 Paint - above sink + Drywall - north wall - holes
#43. Paint – scuffmarks above sink

LOENSER COTTAGE

Varnish – window wells, doors & trim.
Extend sidewalk - form and pour.
Check – rain gutter + nails

ZELLER COTTAGE

Dormer – complete siding – cover fascia w/aluminum.
Extend sidewalk form and pour
Check – rain gutter + nails

POPSTAND

Close south wall crawl space – cement board
Redo/relocate electrical feed to old popstand
Install – light switches.
Check – rain gutter + nails

OLD/NEW SHOP

Repair Metal Roof – Old Shop

CENTER LAVATORY

Lay new shingles
Install Rain Gutter

As ALWAYSBethel Park..... is the place to be!!

**Why not make plans to attend? It is a wonderful opportunity
to spend time with friends and family!**

Please inform us of your coming! Call: **269-465-6669**

or email: ddr@qtm.net

WELCOME - WILLKOMMEN!!
